

Amps 1	Volts1	Volts2	Watts IN 1	PF 1	Efficiency	Speed [RPM]	Torque [oz.in]	Horsepower	Time
0.387000	123.275000	36.140000	0.757000	0.081000	1943.000000	2.029000	0.004000	0.000000	
0.389000	123.245000	36.910000	0.770500	0.079500	1936.000000	2.049500	0.004000	0.130000	
0.388500	123.244500	36.974500	0.772000	0.081500	1935.000000	2.104000	0.004000	0.200000	
0.388500	123.237000	36.950500	0.771500	0.083500	1931.000000	2.156500	0.004000	0.240000	
0.389000	123.228000	36.790500	0.768000	0.084500	1926.000000	2.179000	0.004000	0.250000	
0.388000	123.189500	36.943000	0.772500	0.089000	1923.000000	2.313500	0.004500	0.280000	
0.389000	123.207000	37.116500	0.774500	0.093500	1920.000000	2.448500	0.005000	0.310000	
0.388750	123.188500	37.012000	0.773250	0.094750	1918.000000	2.474000	0.005000	0.340000	
0.388000	123.147500	36.970000	0.773500	0.094500	1914.000000	2.467000	0.005000	0.370000	
0.388400	123.167600	37.083900	0.774700	0.095000	1909.000000	2.492600	0.005000	0.390000	
0.388000	123.155000	36.997500	0.773500	0.096000	1905.000000	2.525000	0.005000	0.410000	
0.389000	123.185000	37.035500	0.773000	0.101000	1901.000000	2.660500	0.005000	0.440000	
0.389000	123.208500	37.112000	0.774500	0.102000	1896.000000	2.703500	0.005000	0.471000	
0.389500	123.198000	37.214500	0.776000	0.102000	1896.000000	2.708500	0.005000	0.491000	
0.390000	123.182500	37.277000	0.777000	0.103000	1891.000000	2.738000	0.005000	0.521000	
0.389500	123.203000	37.204000	0.776000	0.103500	1891.000000	2.753000	0.005000	0.531000	
0.390000	123.216500	37.211000	0.775500	0.104000	1888.000000	2.777000	0.005000	0.551000	
0.390000	123.183000	37.358333	0.777667	0.106833	1882.000000	2.863833	0.005000	0.581000	
0.391000	123.235500	37.453000	0.777500	0.107500	1877.000000	2.894500	0.005000	0.611000	
0.390000	123.186000	37.394500	0.779000	0.108000	1879.000000	2.911000	0.005500	0.631000	
0.391000	123.223000	37.400250	0.777250	0.109250	1874.000000	2.945750	0.005500	0.661000	
0.391500	123.235167	37.748278	0.782500	0.109444	1867.000000	2.989389	0.005722	0.671000	
0.391000	123.231500	37.433167	0.777500	0.111167	1865.000000	3.015333	0.005833	0.691000	
0.391000	123.229167	37.407333	0.776833	0.114000	1860.000000	3.092667	0.006000	0.731000	
0.391000	123.232667	37.409333	0.776333	0.114000	1860.000000	3.100167	0.006000	0.751000	
0.391167	123.222667	37.664833	0.781833	0.113833	1855.000000	3.134333	0.006000	0.761000	
0.391083	123.221833	37.665167	0.781917	0.114417	1854.000000	3.141167	0.006000	0.781000	
0.391000	123.193500	37.612500	0.781500	0.117333	1848.000000	3.230500	0.006000	0.801000	
0.391000	123.198000	37.642000	0.782000	0.117000	1850.000000	3.220000	0.006000	0.811000	
0.391000	123.182500	37.694000	0.782500	0.118833	1848.000000	3.273000	0.006000	0.841000	
0.392083	123.238583	37.849417	0.783250	0.120500	1843.000000	3.341750	0.006000	0.871000	

Save Data

Configure Print

Print